

## **PODCAST**

## **Top 10 Estimating Mistakes & Paint Failures**

WITH BOB CUSUMANO

1	Bad Math	NOTES:
2	IMPROPER assessment of the amount of surface preparation that is required	
3	FAILURE to reference PCA standards in proposals and contracts	
4	<b>FAILURE</b> to <b>track production rates</b> that you achieve on your jobs	
5	FAILURE to pick up <b>important details</b> on the drawings	
6	IMPROPER assessment of your company's overhead	
7	<b>FAILURE</b> to perform <b>adhesion test</b> when doing repaint jobs	
8	FAILURE to read general conditions	
9	<b>FAILURE</b> to read all the <b>technical sections</b> of the specifications	
10	FAILURE to recognize additional job costs	

